WA-II-491 Frame House

Early 20th century

Benevola Vicinity

Private

The Frame House is a two-story, three-bay by two-bay structure with a gable roof. The main facade has a full-length, one-story front porch supported by Tuscan-style columns. The house has a rectangular plan and appears to have been built in the early 20th century.

Maryland Historical Trust State Historic Sites Inventory Form

Magi No.

DOE __yes __no

2.5

1. Nan	1e (indicate pr	eferred name)			
historic					
and/or common	Frame house				
2. Loca	ation				
street & number	r southeast corner	of Alt. 40, and Mil	Incint Road	not for publication	
city, town	bounded collect	Benevola _x_vicinity of	congressional district	sixth	
state Mary	land	county	Washington		
3. Clas	sification				
Category district X building(s) structure site object	Ownership public _X_ private both Public Acquisition in process being considerednot_applicable	Status X occupied unoccupied work in progress Accessible yes: restricted yes: unrestricted no	Present Use agriculture commercial educational entertainment government industrial military	museum park X private residence religious scientific transportation other:	
4. Owr	ner of Prope	rty (give names a	nd mailing addresse	es of <u>all</u> owners)	
name Bil	1 Hapkins				
street & number	-		telephone r	10.:	
		and zip code			
	ation of Leg	al Description			
courthouse, reg	istry of deeds, etc. Was	hington County Cour		liber	
street & number	Washington Stree	t		folio	
	agerstown	in Foliation	state	Maryland	
6. Rep	resentation	IN EXISTING	Historical Surv	veys	
<u>`!tle</u>					
date			federal sta	te county local	
depository for s	urvey records				
city, town			state		

Survey No.WA-II-491

Condition excellent deteriorated good ruins fair unexposed	Check one unaltered altered	Check one original site moved date of move	
--	-----------------------------	--	--

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The frame house is a two-story, three-bay by two-bay structure with a gable roof. The main facade has a full-length, one-story front porch supported by Tuscan-style columns. The house has a rectangular plan and appears to have been built in the early 20th century.

The house is located on the southeast corner of the Alt. Rt. 40 and Millpoint Road, near Benevola. The house is sited on a small lot adjoining the lot of another house that is covered in sheet metal. Sheet metal also covers the gable roof of the house. Brick interior-end chimneys are located at each gable end at the peak of the roof. The north and south facades have two windows on each story and two small windows in the gable. There is also an entrance at the rear of the southern gable end. The house is covered in a white aluminum siding.

There are no significant outbuildings on the property.

0. 3	olgn	ificance		Survey No.WA-II-4	91
reriod	1499 1599 1699 1699 1699 1699	archeology-historic agriculture architecture	heck and justify below community planning conservation economics education engineering exploration/settlement industry invention	literature military music philosophy politics/government	religion science sculpture social/ humanitarian theater transportation other (specify)
Specific	dates		Builder/Architect		
check:	ar Appli	cable Criteria:A nd/or cable Exception:A of Significance:	BCDF		
Prepare support	both			a general statement of	history and
	a M	ed on the MHT Survid-level site that egrity from exteri	; has loss some a	rchitectural	

10. G	eographical	Data				
Acreage of no Quadrangle no UTM Reference					Quadrangl	e scale
A	sting Northing		B Zone	Eas	ting	Northing
C			D			
Verbal boun	dary description and just	tification	· · · · · · · · · · · · · · · · · · ·			
	es and counties for prope			count	y boundaries	code
state			unty			code
	orm Prepared					
name/title	Joe Getty					
organization	Maryland Historical	Trust		date	May 1983	
street & numb	er 21 State Circle			teleph	one	
city or town	Annapolis		-,	state	Maryland	

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:


Maryland Historical Trust

Shaw House

21 State Circle

Annapolis, Maryland 21401

(301) 269-2438





- Frame House WA-II-491
- Washington County, Maryland
- 3. Joe Getty
- 4. May 1983
- 5. Maryland Hist. Trust, Annapolis, Md.
- 6. West & north elevations; camera facing southeast 7. 1/1